
# NX DESIGN ASSOCIATE CERTIFICATION PRACTICE EXAM (SAMPLE)

## STUDY GUIDE




## SAMPLE STUDY GUIDE WITH LIMITED QUESTIONS

**VISIT US ONLINE FOR THE FULL VERSION STUDY GUIDE**

https://nxdesignassociate.examzify.com

**Copyright © 2026 by Examzify - A Kaluba Technologies Inc. product.**

**ALL RIGHTS RESERVED.**

No part of this book may be reproduced or transferred in any form or by any means, graphic, electronic, or mechanical, including photocopying, recording, web distribution, taping, or by any information storage retrieval system, without the written permission of the author.

Notice: Examzify makes every reasonable effort to obtain accurate, complete, and timely information about this product from reliable sources.

SAMPLE

# Table of Contents


Copyright ..... 1

Table of Contents ..... 2

Introduction ..... 3

How to Use This Guide ..... 4

Questions ..... 5

Answers ..... 8

Explanations ..... 10

Next Steps ..... 16


SAMPLE

# Introduction

Preparing for a certification exam can feel overwhelming, but with the right tools, it becomes an opportunity to build confidence, sharpen your skills, and move one step closer to your goals. At Examzify, we believe that effective exam preparation isn't just about memorization, it's about understanding the material, identifying knowledge gaps, and building the test-taking strategies that lead to success.

This guide was designed to help you do exactly that.

Whether you're preparing for a licensing exam, professional certification, or entry-level qualification, this book offers structured practice to reinforce key concepts. You'll find a wide range of multiple-choice questions, each followed by clear explanations to help you understand not just the right answer, but why it's correct.

The content in this guide is based on real-world exam objectives and aligned with the types of questions and topics commonly found on official tests. It's ideal for learners who want to:

- Practice answering questions under realistic conditions,
- Improve accuracy and speed,
- Review explanations to strengthen weak areas, and
- Approach the exam with greater confidence.

We recommend using this book not as a stand-alone study tool, but alongside other resources like flashcards, textbooks, or hands-on training. For best results, we recommend working through each question, reflecting on the explanation provided, and revisiting the topics that challenge you most.

Remember: successful test preparation isn't about getting every question right the first time, it's about learning from your mistakes and improving over time. Stay focused, trust the process, and know that every page you turn brings you closer to success.

Let's begin.

SAMPLE

# How to Use This Guide

This guide is designed to help you study more effectively and approach your exam with confidence. Whether you're reviewing for the first time or doing a final refresh, here's how to get the most out of your Examzify study guide:

### 1. Start with a Diagnostic Review

Skim through the questions to get a sense of what you know and what you need to focus on. Your goal is to identify knowledge gaps early.

### 2. Study in Short, Focused Sessions

Break your study time into manageable blocks (e.g. 30 – 45 minutes). Review a handful of questions, reflect on the explanations.

### 3. Learn from the Explanations

After answering a question, always read the explanation, even if you got it right. It reinforces key points, corrects misunderstandings, and teaches subtle distinctions between similar answers.

### 4. Track Your Progress

Use bookmarks or notes (if reading digitally) to mark difficult questions. Revisit these regularly and track improvements over time.

### 5. Simulate the Real Exam

Once you're comfortable, try taking a full set of questions without pausing. Set a timer and simulate test-day conditions to build confidence and time management skills.

### 6. Repeat and Review

Don't just study once, repetition builds retention. Re-attempt questions after a few days and revisit explanations to reinforce learning. Pair this guide with other Examzify tools like flashcards, and digital practice tests to strengthen your preparation across formats.

There's no single right way to study, but consistent, thoughtful effort always wins. Use this guide flexibly, adapt the tips above to fit your pace and learning style. You've got this!

SAMPLE

# Questions

SAMPLE

**1. What is the main purpose of 3D scanning data in NX?**

A. To create 2D representations of existing models

B. To replicate the surfaces of scanned objects into CAD

C. To analyze the environmental impact of designs

D. To perform cost estimations on manufacturing

**2. After using the Show Dimensions command on a sketch, how do you erase the temporarily-displayed dimensions from the graphics window?**

A. Close the Sketch

B. Use the Refresh command

C. Reopen the dimension settings

D. Click on a different feature

**3. What is a key difference between a Design Group and Feature Group?**

A. A Design Group can control the updating of the model

B. A Design Group contains only aesthetic features

C. A Feature Group is limited to sketches

D. A Feature Group can only contain solid bodies

**4. What is the function of design history in NX?**

A. It generates automated reports for project milestones

B. It records and allows for modification of previous design steps to improve or alter designs

C. It tracks the time taken for each design process

D. It visualizes the design changes in real-time

**5. In the context of assembly design, what is meant by "the work part"?**

A. The entire assembly

B. The displayed part being edited

C. The base component

D. The reference component

SAMPLE

**6. What is one reason to use Visual Reporting in an assembly?**

A. To synchronize components

B. To color-code the assembly to summarize a specific condition

C. To automatically update part dimensions

D. To eliminate unnecessary components

**7. In the Part Navigator, how can you list the parameters, expressions, and values of a feature without using the Show Dimensions command?**

A. Open the Properties Panel

B. Open the Details Group

C. Select the Feature and press F1

D. Right-click and choose Show Parameters

**8. Which command displays the number of rotational and transitional degrees that a component can move in an assembly?**

A. Show Toggle States

B. Show Degrees of Freedom

C. Show Component Properties

D. Show Assembly Constraints

**9. How can you investigate the design intent of a sketch?**

A. Inspect the Sketch Properties

B. Vary a dimension to see how the sketch changes

C. Export the Sketch

D. Adjust the View Angle

**10. How do you use the "Mirror" feature in NX?**

A. To apply patterns to existing sketches

B. To create a symmetrical copy of selected geometry across a defined plane

C. To replicate the entire structure of an assembly

D. To simplify complex 3D models

SAMPLE

# Answers

SAMPLE

1. B
2. B
3. A
4. B
5. B
6. B
7. B
8. B
9. B
10. B

SAMPLE

# Explanations

SAMPLE

## 1. What is the main purpose of 3D scanning data in NX?

A. To create 2D representations of existing models

B. To replicate the surfaces of scanned objects into CAD

C. To analyze the environmental impact of designs

D. To perform cost estimations on manufacturing

*The primary purpose of 3D scanning data in NX is to replicate the surfaces of scanned objects into computer-aided design (CAD) models. This capability allows designers and engineers to capture the precise geometry of physical objects, which can then be utilized in CAD software for further design modifications, simulations, or integration into larger assemblies. By converting real-world tactile objects into digital formats, 3D scanning ensures accuracy in modeling, facilitating more effective design processes and product development. For context, creating 2D representations does not utilize the unique benefits of 3D scanning, as the primary advantage lies in capturing three-dimensional data. Analyzing the environmental impact of designs and performing cost estimations are broader assessments not inherently tied to the capabilities of 3D scanning in NX, focusing instead on different aspects of the design and manufacturing processes.*

## 2. After using the Show Dimensions command on a sketch, how do you erase the temporarily-displayed dimensions from the graphics window?

A. Close the Sketch

B. Use the Refresh command

C. Reopen the dimension settings

D. Click on a different feature

*The Refresh command is the appropriate action to erase temporarily-displayed dimensions from the graphics window after using the Show Dimensions command on a sketch. When you utilize the Show Dimensions feature, dimensions appear on the screen for reference but are not intended to remain visible indefinitely. By executing the Refresh command, you prompt the software to update the display, effectively removing those temporary dimensions and returning the graphics window to its previous state. Employing other options like closing the sketch or reopening dimension settings would not specifically target the removal of the temporary dimensions created by the Show Dimensions command. Clicking on a different feature could also serve to change the focus of the display, but it does not specifically reset the visibility of the dimensions displayed. Thus, using the Refresh command directly addresses the intent of removing those temporary annotations from the view efficiently.*

## 3. What is a key difference between a Design Group and Feature Group?

A. A Design Group can control the updating of the model

B. A Design Group contains only aesthetic features

C. A Feature Group is limited to sketches

D. A Feature Group can only contain solid bodies

*A Design Group is primarily used to manage and control the updating of the model as it allows for better organization and manipulation of features within the model. It provides a way to group together multiple features, thus making it easier to edit or update a set of features simultaneously. This capability is particularly beneficial when dealing with complex models where certain characteristics must be maintained while changes are made to others. On the other hand, the other options do not accurately reflect the functionalities of Design Groups and Feature Groups. Design Groups are not limited to aesthetic features, nor are Feature Groups restricted to just sketches. Additionally, Feature Groups can include a wider variety of features beyond just solid bodies; they can also encompass operations like holes and rounds. Therefore, the ability of a Design Group to control the updating process is a significant distinction that enhances workflow efficiency in design modification processes.*

SAMPLE

## 4. What is the function of design history in NX?

A. It generates automated reports for project milestones

B. It records and allows for modification of previous design steps to improve or alter designs

C. It tracks the time taken for each design process

D. It visualizes the design changes in real-time

*The function of design history in NX is pivotal to the design process, as it records and allows for the modification of previous design steps. This capability is essential because it enables designers to revisit past versions of their work, make changes, and improve upon existing designs. This feature fosters a non-linear approach to design, where alterations can be made at any stage of the process without the need to start over. The history function is crucial for collaborating with team members who may need to review past iterations, and it provides a clear trail of modifications which can be beneficial for documentation and design validation. The other options do not accurately represent the primary purpose of design history in NX. While generating reports, tracking time, or visualizing changes may be useful functions in a design setting, they do not encapsulate the primary role of design history, which is focused on maintaining a record of design modifications and supporting iterative design processes.*

## 5. In the context of assembly design, what is meant by "the work part"?

A. The entire assembly

B. The displayed part being edited

C. The base component

D. The reference component

*In assembly design, "the work part" specifically refers to the displayed part that is currently being edited. This term is used to identify the part that the designer is actively working on within the assembly environment. When making modifications, the design software focuses on the work part, allowing the user to make changes that will affect that specific component. The work part is crucial because it allows for a clear distinction between the different components of an assembly. While the entire assembly is comprised of various parts, only the work part is subject to immediate edits and alterations. This makes it easier for designers to manage complex assemblies, ensuring that they are concentrating on a single part at a time while visualizing how it interacts with the rest of the assembly. In this context, the base component or reference component might play specific roles in the overall design, but they do not represent the part currently under direct modification. Understanding this concept is vital for efficient assembly design and management within CAD applications.*

SAMPLE

## 6. What is one reason to use Visual Reporting in an assembly?

A. To synchronize components

B. To color-code the assembly to summarize a specific condition

C. To automatically update part dimensions

D. To eliminate unnecessary components

*Using Visual Reporting in an assembly allows for the color-coding of components to visually summarize specific conditions or attributes. This feature enhances the clarity and organization of complex assemblies, making it easier for designers and engineers to quickly identify components that meet certain criteria, are at risk, or have specific characteristics. For instance, color-coding can be used to indicate which parts are under constrained conditions or which ones might need attention, thereby facilitating effective management of the assembly process. The other options do not directly relate to the primary function of Visual Reporting. For example, synchronizing components involves aligning their movements or behaviors rather than summarizing data visually, while automatically updating part dimensions pertains more to design parameters than reporting visibility. Additionally, eliminating unnecessary components relates to optimizing the assembly's design rather than visually representing or summarizing data conditions.*

## 7. In the Part Navigator, how can you list the parameters, expressions, and values of a feature without using the Show Dimensions command?

A. Open the Properties Panel

B. Open the Details Group

C. Select the Feature and press F1

D. Right-click and choose Show Parameters

*To list the parameters, expressions, and values of a feature in the Part Navigator, opening the Details Group is the correct approach. This functionality allows you to view additional information about the selected feature in more detail. When you access the Details Group, the parameters and expressions that define the feature will be displayed clearly, making it easy to review and understand how the feature is constructed. This method provides relevant insights directly related to the selected feature without requiring any additional navigation or commands. It's an efficient way to access specific information that might be crucial for further design decisions or modifications within the modeling workflow. Other options like using the Properties Panel typically focus on the overall properties of the part rather than the specific parameters of a feature. Selecting the feature and pressing F1 brings up the help documentation rather than detailing feature parameters. Right-clicking and choosing Show Parameters is indeed another way to access this information, but it is not as direct as utilizing the Details Group, which provides a comprehensive view in one location.*

SAMPLE

## 8. Which command displays the number of rotational and transitional degrees that a component can move in an assembly?

A. Show Toggle States

B. Show Degrees of Freedom

C. Show Component Properties

D. Show Assembly Constraints

*The command that displays the number of rotational and translational degrees of freedom for a component within an assembly is the command that identifies the available movements of that component. This means it indicates how many ways the component can move based on the constraints applied to it within the assembly environment. Degrees of freedom refer to the different ways in which a component can move in three-dimensional space. This includes translational movements along the X, Y, and Z axes as well as rotational movements about those axes. Understanding the degrees of freedom is essential in assembly design because it allows engineers and designers to know how components interact and move relative to each other, thereby ensuring mechanical functionality and proper operation. The other options do not specifically provide this information about the movement capabilities of components. For example, while showing toggle states might indicate visibility or scenario changes, it does not address movement. Showing component properties may present various characteristics of the component such as material or size, but it does not cover degrees of freedom. Similarly, showing assembly constraints focuses on the specific limitations imposed on the components by constraints, rather than summarizing their possible movement ranges. Therefore, the command that accurately provides the desired information about movement potential is the one that shows degrees of freedom.*

## 9. How can you investigate the design intent of a sketch?

A. Inspect the Sketch Properties

B. Vary a dimension to see how the sketch changes

C. Export the Sketch

D. Adjust the View Angle

*To investigate the design intent of a sketch, varying a dimension to observe how the sketch changes is a practical and effective method. This approach allows you to see the relationships and constraints that govern the sketch's geometry. By adjusting specific dimensions, you can ascertain how they influence the overall shape and features of the sketch, revealing the underlying logic and purpose behind its design. When you change a dimension and note the resulting alterations in the sketch, you're engaging with its constraints and dependencies, which are pivotal in understanding the design intent. This interaction provides insights into how different elements are linked and how modifications could affect the broader design. Inspecting the Sketch Properties can provide useful information about the dimensions and constraints but does not actively demonstrate how adjustments impact the sketch in real-time. Exporting the sketch doesn't serve to clarify design intent; rather, it simply relocates the sketch without interaction. Adjusting the view angle might help visualize the sketch from different perspectives, but it does not directly influence or reveal the relationships and intent embedded within the sketch itself. Thus, varying a dimension is the most effective means of understanding the design intent behind a sketch.*

SAMPLE

## 10. How do you use the "Mirror" feature in NX?

A. To apply patterns to existing sketches

B. To create a symmetrical copy of selected geometry across a defined plane

C. To replicate the entire structure of an assembly

D. To simplify complex 3D models

*Using the "Mirror" feature in NX is fundamentally about creating a symmetrical copy of selected geometry across a defined plane. This feature is particularly useful in design situations where symmetry is an integral part of the component, such as in mechanical parts, architectural elements, or any design requiring symmetry. When utilizing the Mirror tool, you select the geometry you want to mirror, and then specify a plane of symmetry. The resulting mirrored geometry is an exact reflection of the original across that plane, ensuring precision and consistency in the design. This capability allows designers to save time and avoid errors that might occur if they were to manually recreate the mirrored components. The other options focus on different functionalities within NX. Applying patterns to existing sketches pertains to the patterning tools that replicate features but do not specifically create mirrored copies. Replicating the entire structure of an assembly is more related to assembly management and arrangement than the specific action of mirroring. Simplifying complex 3D models generally involves techniques aimed at reducing the polygon count or optimizing models for performance, which does not align with the primary function of the Mirror feature.*

SAMPLE

# Next Steps

Congratulations on reaching the final section of this guide. You've taken a meaningful step toward passing your certification exam and advancing your career.

As you continue preparing, remember that consistent practice, review, and self-reflection are key to success. Make time to revisit difficult topics, simulate exam conditions, and track your progress along the way.

If you need help, have suggestions, or want to share feedback, we'd love to hear from you. Reach out to our team at hello@examzify.com.

Or visit your dedicated course page for more study tools and resources:

https://nxdesignassociate.examzify.com

We wish you the very best on your exam journey. You've got this!

SAMPLE