
SOLID EDGE ASSOCIATE LEVEL PRACTICE EXAM (SAMPLE)

STUDY GUIDE



SAMPLE STUDY GUIDE WITH LIMITED QUESTIONS

VISIT US ONLINE FOR THE FULL VERSION STUDY GUIDE

https://solidedgeassoclevel.examzify.com

Copyright © 2026 by Examzify - A Kaluba Technologies Inc. product.

ALL RIGHTS RESERVED.

No part of this book may be reproduced or transferred in any form or by any means, graphic, electronic, or mechanical, including photocopying, recording, web distribution, taping, or by any information storage retrieval system, without the written permission of the author.

Notice: Examzify makes every reasonable effort to obtain accurate, complete, and timely information about this product from reliable sources.

SAMPLE

Table of Contents

Copyright 1

Table of Contents 2

Introduction 3

How to Use This Guide 4

Questions 5

Answers 8

Explanations 10

Next Steps 16

SAMPLE

Introduction

Preparing for a certification exam can feel overwhelming, but with the right tools, it becomes an opportunity to build confidence, sharpen your skills, and move one step closer to your goals. At Examzify, we believe that effective exam preparation isn't just about memorization, it's about understanding the material, identifying knowledge gaps, and building the test-taking strategies that lead to success.

This guide was designed to help you do exactly that.

Whether you're preparing for a licensing exam, professional certification, or entry-level qualification, this book offers structured practice to reinforce key concepts. You'll find a wide range of multiple-choice questions, each followed by clear explanations to help you understand not just the right answer, but why it's correct.

The content in this guide is based on real-world exam objectives and aligned with the types of questions and topics commonly found on official tests. It's ideal for learners who want to:

- Practice answering questions under realistic conditions,
- Improve accuracy and speed,
- Review explanations to strengthen weak areas, and
- Approach the exam with greater confidence.

We recommend using this book not as a stand-alone study tool, but alongside other resources like flashcards, textbooks, or hands-on training. For best results, we recommend working through each question, reflecting on the explanation provided, and revisiting the topics that challenge you most.

Remember: successful test preparation isn't about getting every question right the first time, it's about learning from your mistakes and improving over time. Stay focused, trust the process, and know that every page you turn brings you closer to success.

Let's begin.

SAMPLE

How to Use This Guide

This guide is designed to help you study more effectively and approach your exam with confidence. Whether you're reviewing for the first time or doing a final refresh, here's how to get the most out of your Examzify study guide:

1. Start with a Diagnostic Review

Skim through the questions to get a sense of what you know and what you need to focus on. Your goal is to identify knowledge gaps early.

2. Study in Short, Focused Sessions

Break your study time into manageable blocks (e.g. 30 – 45 minutes). Review a handful of questions, reflect on the explanations.

3. Learn from the Explanations

After answering a question, always read the explanation, even if you got it right. It reinforces key points, corrects misunderstandings, and teaches subtle distinctions between similar answers.

4. Track Your Progress

Use bookmarks or notes (if reading digitally) to mark difficult questions. Revisit these regularly and track improvements over time.

5. Simulate the Real Exam

Once you're comfortable, try taking a full set of questions without pausing. Set a timer and simulate test-day conditions to build confidence and time management skills.

6. Repeat and Review

Don't just study once, repetition builds retention. Re-attempt questions after a few days and revisit explanations to reinforce learning. Pair this guide with other Examzify tools like flashcards, and digital practice tests to strengthen your preparation across formats.

There's no single right way to study, but consistent, thoughtful effort always wins. Use this guide flexibly, adapt the tips above to fit your pace and learning style. You've got this!

SAMPLE

Questions

SAMPLE

1. Which tool allows a sketch or body to be projected while adding depth?

A. Revolve

B. Extrude

C. Offset

D. Project

2. What term describes how various parts of an assembly connect together?

A. Assembly structure

B. Connection

C. Explosion

D. Assembly design

3. What feature is used to break a sharp corner in a design?

A. Fillet

B. Radius

C. Chamfer

D. Bevel

4. In assembly drawing views, what does changing balloon distance affect?

A. The model's overall dimensions

B. The visual clarity of the assembly

C. The placement of annotation balloons

D. The material properties displayed

5. How does GDandT ensure parts fit together in assembly?

A. By detailing aesthetic features

B. By specifying geometric tolerances

C. By visualizing part motions

D. By generating 2D draft layouts

6. Which file format is used by Solid Edge for parts?

A. .asm

B. .dxf

C. .par

D. .stl

SAMPLE

7. Where can you find the Face Relate commands in Solid Edge?

A. Home tab

B. Inspect tab

C. View tab

D. Tools tab

8. Which option should you select to lock to a sketch plane in the PathFinder?

A. Lock Sketch Plane

B. Attach Sketch

C. Set Sketch Plane

D. Align to Sketch Plane

9. What shortcut enables switching from Add to Cut (remove) mode?

A. Control key

B. Shift key

C. Spacebar

D. Tab key

10. What must be added first to create a section view in a drawing?

A. A Cut List

B. A Section Line

C. A Cutting Plane

D. An Isometric View

SAMPLE

Answers

SAMPLE

1. B
2. C
3. C
4. C
5. B
6. C
7. A
8. A
9. C
10. C

SAMPLE

Explanations

SAMPLE

1. Which tool allows a sketch or body to be projected while adding depth?

A. Revolve

B. Extrude

C. Offset

D. Project

The tool that allows a sketch or body to be projected while adding depth is the extrude command. When you use the extrude function in Solid Edge, it takes a 2D sketch and adds depth to it, creating a 3D solid shape. This transformation involves extending the sketch vertically or along a specified path, resulting in three-dimensional geometry. The extrude operation can be applied to various shapes, effectively allowing users to create complex parts from simple sketches. The depth of the extrusion can typically be specified by the user, making it highly versatile for modeling different components. In contrast, while a revolve command can create a 3D shape by rotating a sketch around an axis, it does not directly project a sketch in the same manner as extrude does. The offset tool is useful for creating parallel copies of curves or edges but does not add depth or convert 2D shapes into 3D forms. The project tool is primarily used for projecting geometry onto a different plane or surface rather than for adding depth to a sketch.

2. What term describes how various parts of an assembly connect together?

A. Assembly structure

B. Connection

C. Explosion

D. Assembly design

The term that accurately describes how various parts of an assembly connect together is "Connection." In the context of assemblies, connections refer to the methods or points at which different components join or interface with each other, resulting in a cohesive working model. Connections can involve various forms, such as bolt holes, dovetails, or pins, to ensure that parts work in unison and maintain the intended assembly functionality. The assembly structure pertains to the overall organization and hierarchy of the components within an assembly but does not specifically address the details of how those components connect. Similarly, "Explosion" typically refers to an exploded view of an assembly for illustrative purposes, showing how parts fit together without conveying the specifics of their connection. "Assembly design," while related to the overall process of creating an assembly, focuses on broader design aspects rather than the critical specifics of component connections. Thus, "Connection" is the most precise term in this context.

SAMPLE

3. What feature is used to break a sharp corner in a design?

A. Fillet

B. Radius

C. Chamfer

D. Bevel

The feature used to break a sharp corner in a design is the chamfer. A chamfer creates a straight-edge transition between two surfaces, effectively removing the sharp corner and replacing it with an angled edge. This can enhance both the appearance and functionality of a part by reducing stress concentrations, which can lead to fractures or failures. Chamfers are particularly useful in applications where parts need to fit together or where a smooth transition is desired for safety reasons, such as in mechanical components or user interfaces. The angle of the chamfer can often be specified during the design process, allowing for flexibility based on the specific requirements of the part. In contrast, a fillet creates a rounded edge, while a radius refers to the specific measurement of that curve. A bevel, while similar in that it also removes sharp edges, typically refers to an angle cut that creates a sloped surface—often more applicable in joining two components rather than simply softening a corner. Understanding these distinctions is key for effective design practices in Solid Edge and similar CAD applications.

4. In assembly drawing views, what does changing balloon distance affect?

A. The model's overall dimensions

B. The visual clarity of the assembly

C. The placement of annotation balloons

D. The material properties displayed

Changing the balloon distance in assembly drawing views primarily affects the placement of annotation balloons. Annotation balloons are used to reference components in the assembly, and their distance from the respective parts can impact how clearly the assembly is understood. Adjusting the distance can help to avoid overlaps with other elements in the drawing, ensuring that each balloon clearly indicates its corresponding part without confusion or clutter. This adjustment is crucial for maintaining effective communication of information in technical drawings, especially in complex assemblies. The other options relate to aspects that are not directly influenced by the balloon distance. For example, the overall dimensions of the model or the material properties displayed remain unaffected by how far the balloons are placed from the components. Similarly, while the visual clarity of the assembly can be influenced indirectly by the placement of balloons, it is specifically the balloon distance that determines where these reference points are situated relative to the parts they annotate.

SAMPLE

5. How does GDandT ensure parts fit together in assembly?

A. By detailing aesthetic features

B. By specifying geometric tolerances

C. By visualizing part motions

D. By generating 2D draft layouts

Geometric Dimensioning and Tolerancing (GD&T) plays a crucial role in ensuring that parts fit together correctly in an assembly by providing a clear and concise method for specifying the allowable variations in part features. This system defines how parts should be dimensioned and toleranced, allowing engineers and manufacturers to understand the acceptable limits of size, shape, orientation, and location of features on a part. Through the use of symbols and annotations, GD&T communicates critical information about the relationships between different features of a component. This ensures that even if parts are manufactured with slight variations, they can still be assembled together as intended without issues. For instance, features such as datums, which serve as a reference point for measuring other features, are key in establishing how parts relate to one another in three-dimensional space. The other approaches mentioned, such as detailing aesthetic features, visualizing part motions, and generating 2D draft layouts, do not address the functional requirements of maintaining proper fit and alignment in assemblies. While they may contribute to the overall design process, they do not provide the specific standards and controls that GD&T offers for ensuring that parts interact correctly in assemblies. Therefore, specifying geometric tolerances is essential for precise manufacturing and successful assembly of components.

6. Which file format is used by Solid Edge for parts?

A. .asm

B. .dxf

C. .par

D. .stl

Solid Edge uses the .par file format for parts. This file extension specifically denotes a part file in Solid Edge, which contains all the necessary data regarding the component's geometry, properties, and features. Each .par file serves as an integral building block for assemblies or drawings, allowing users to create detailed 3D models and store pertinent information about the individual part. The other file formats serve different purposes within the realm of CAD and design applications. For instance, .asm files are used for assembly files, .dxf is a format typically employed for 2D drawings and interoperability purposes, and .stl is primarily utilized for 3D printing and rapid prototyping as it represents the surface geometry of 3D objects without any CAD-specific data. Therefore, .par is uniquely suited for part modeling in Solid Edge.

SAMPLE

7. Where can you find the Face Relate commands in Solid Edge?

A. Home tab

B. Inspect tab

C. View tab

D. Tools tab

The Face Relate commands in Solid Edge can be found on the Home tab. This is because the Home tab is designed to house fundamental operations related to modeling and design, which include the manipulation and relationship management of faces in 3D geometric modeling. The Face Relate commands are essential when working on assemblies or part design, as they help to establish and control geometric relationships between different faces, thus facilitating accurate alignment and positioning of components. The other options typically contain functionalities that support specific tasks but do not focus directly on the fundamental operations of modeling where Face Relate commands are categorized. For instance, the Inspect tab usually contains tools for evaluating models, while the View tab is focused on display settings and visualization commands. The Tools tab often includes utilities and settings rather than primary modeling commands. Hence, the Home tab is the most logical and appropriate location for the Face Relate commands.

8. Which option should you select to lock to a sketch plane in the PathFinder?

A. Lock Sketch Plane

B. Attach Sketch

C. Set Sketch Plane

D. Align to Sketch Plane

To lock a sketch plane in the PathFinder, the appropriate selection is to "Lock Sketch Plane." This option is specifically designed to secure the sketch to a defined plane, ensuring that any modifications made to the sketch maintain its association with that plane throughout the design process. This is particularly important in 3D modeling environments where maintaining the orientation and position of a sketch is crucial for subsequent modeling features like extrudes or revolves. By locking the sketch plane, you prevent unintended movements or alterations that could occur if the sketch were simply attached or aligned without this level of control. The other options, while related to sketching functionality, do not provide the same level of permanence in terms of securing the sketch to a specific plane. "Attach Sketch" is typically about creating a connection to a feature rather than locking down the entire sketch to a specific orientation. "Set Sketch Plane" refers to selecting a plane for the sketch rather than locking it, which implies you can still modify or change that setting afterward. "Align to Sketch Plane" suggests positioning an element relative to a sketch plane but does not imply a locking mechanism. Hence, choosing "Lock Sketch Plane" is the precise action needed to ensure the stability and integrity of the sketch in relation to its designated plane

SAMPLE

9. What shortcut enables switching from Add to Cut (remove) mode?

A. Control key

B. Shift key

C. Spacebar

D. Tab key

The Spacebar serves as a shortcut for toggling between Add and Cut modes in Solid Edge. This allows users to quickly switch their selection mode while working with features like creating or modifying parts and assemblies. Having an efficient way to switch modes helps streamline the design process, enabling users to make adjustments without having to navigate through multiple menus or commands, thereby enhancing workflow and productivity. The other options do not provide the same functionality in Solid Edge. For example, the Control key is often used for various commands, including selecting multiple elements, while the Shift key typically facilitates functions like adding to a selection. The Tab key is generally associated with cycling through different input fields or options, not mode switching. This distinction highlights the unique role of the Spacebar in enhancing user efficiency within the software.

10. What must be added first to create a section view in a drawing?

A. A Cut List

B. A Section Line

C. A Cutting Plane

D. An Isometric View

To create a section view in a drawing, the first step is to establish a cutting plane, which is a graphical representation indicating where the view will be "cut" to reveal the interior details of the object. This cutting plane serves as a guideline for generating the section view, indicating the specific area of the object that will be illustrated and displayed in detail. Without this crucial element, there would be no basis for the section view, rendering it impossible to effectively showcase the internal features of the part being represented. The other options may play a role in the overall drawing but are not the foundational step for creating a section view. For instance, a section line is used to indicate where the cut takes place but comes after defining the cutting plane. A cut list relates to inventory or parts management and is not relevant to section views. An isometric view provides a different perspective of the object entirely and does not contribute to the process of creating a section view. Thus, starting with a cutting plane is essential for accurately depicting the internal elements in a section view.

SAMPLE

Next Steps

Congratulations on reaching the final section of this guide. You've taken a meaningful step toward passing your certification exam and advancing your career.

As you continue preparing, remember that consistent practice, review, and self-reflection are key to success. Make time to revisit difficult topics, simulate exam conditions, and track your progress along the way.

If you need help, have suggestions, or want to share feedback, we'd love to hear from you. Reach out to our team at hello@examzify.com.

Or visit your dedicated course page for more study tools and resources:

https://solidedgeassoclevel.examzify.com

We wish you the very best on your exam journey. You've got this!

SAMPLE