TOOL AND DIE PRACTICE EXAM (SAMPLE)

STUDY GUIDE



SAMPLE STUDY GUIDE WITH LIMITED QUESTIONS

VISIT US ONLINE FOR THE FULL VERSION STUDY GUIDE

https://toolanddie.examzify.com

Copyright © 2026 by Examzify - A Kaluba Technologies Inc. product.

ALL RIGHTS RESERVED.

No part of this book may be reproduced or transferred in any form or by any means, graphic, electronic, or mechanical, including photocopying, recording, web distribution, taping, or by any information storage retrieval system, without the written permission of the author.

Notice: Examzify makes every reasonable effort to obtain accurate, complete, and timely information about this product from reliable sources.

SAMPLE

Table of Contents

Copyright 1

Table of Contents 2

Introduction 3

How to Use This Guide 4

Questions 5

Answers 8

Explanations 10

Next Steps 15

SAMPLE

Introduction

Preparing for a certification exam can feel overwhelming, but with the right tools, it becomes an opportunity to build confidence, sharpen your skills, and move one step closer to your goals. At Examzify, we believe that effective exam preparation isn't just about memorization, it's about understanding the material, identifying knowledge gaps, and building the test-taking strategies that lead to success.

This guide was designed to help you do exactly that.

Whether you're preparing for a licensing exam, professional certification, or entry-level qualification, this book offers structured practice to reinforce key concepts. You'll find a wide range of multiple-choice questions, each followed by clear explanations to help you understand not just the right answer, but why it's correct.

The content in this guide is based on real-world exam objectives and aligned with the types of questions and topics commonly found on official tests. It's ideal for learners who want to:

- Practice answering questions under realistic conditions,
- Improve accuracy and speed,
- Review explanations to strengthen weak areas, and
- Approach the exam with greater confidence.

We recommend using this book not as a stand-alone study tool, but alongside other resources like flashcards, textbooks, or hands-on training. For best results, we recommend working through each question, reflecting on the explanation provided, and revisiting the topics that challenge you most.

Remember: successful test preparation isn't about getting every question right the first time, it's about learning from your mistakes and improving over time. Stay focused, trust the process, and know that every page you turn brings you closer to success.

Let's begin.

SAMPLE

How to Use This Guide

This guide is designed to help you study more effectively and approach your exam with confidence. Whether you're reviewing for the first time or doing a final refresh, here's how to get the most out of your Examzify study guide:

1. Start with a Diagnostic Review

Skim through the questions to get a sense of what you know and what you need to focus on. Your goal is to identify knowledge gaps early.

2. Study in Short, Focused Sessions

Break your study time into manageable blocks (e.g. 30 – 45 minutes). Review a handful of questions, reflect on the explanations.

3. Learn from the Explanations

After answering a question, always read the explanation, even if you got it right. It reinforces key points, corrects misunderstandings, and teaches subtle distinctions between similar answers.

4. Track Your Progress

Use bookmarks or notes (if reading digitally) to mark difficult questions. Revisit these regularly and track improvements over time.

5. Simulate the Real Exam

Once you're comfortable, try taking a full set of questions without pausing. Set a timer and simulate test-day conditions to build confidence and time management skills.

6. Repeat and Review

Don't just study once, repetition builds retention. Re-attempt questions after a few days and revisit explanations to reinforce learning. Pair this guide with other Examzify tools like flashcards, and digital practice tests to strengthen your preparation across formats.

There's no single right way to study, but consistent, thoughtful effort always wins. Use this guide flexibly, adapt the tips above to fit your pace and learning style. You've got this!

SAMPLE

Questions

SAMPLE

1. What lubrication strategies are common in stamping and their effects on wear and finish?

A. Flood or spray lubrication reduces friction and wear and helps control wrinkling and surface finish; dry lubrication can be used for certain materials or speeds but may increase wear

B. Dry lubrication only reduces wear

C. No lubrication reduces wear

D. Grease always reduces wear and improves finish

2. In the described material, which action is explicitly stated as occurring at STEP XI?

A. Piercing and Blanking

B. Honing and Finishing

C. Assembling and Screwing

D. Measuring and Checking

3. Which term defines a press tool or component for receiving blanks?

A. Die Design

B. Stampings

C. Die Block

D. Scrap Strip

4. Which operation smooths wavy edges of drawn metal parts?

A. Shaving

B. Broaching

C. Trimming

D. Horning

5. What is the formula relating cutting speed, spindle speed, and workpiece diameter for turning, and how do you solve for N?

A. V equals pi times D times N divided by 1000, and N equals 1000 V divided by (pi D).

B. V equals D times N divided by pi, and N equals pi D V divided by 1000.

C. V equals 2 pi D N, and N equals V divided by (2 pi D).

D. V equals pi D N divided by 1000, and N equals 1000 V divided by (pi D).

SAMPLE

6. How would you select lubricant viscosity for a stamping operation?

A. Choose lubricant based on color and scent.

B. Use the lightest possible lubricant regardless of process.

C. Rely on trial-and-error to determine viscosity.

D. Follow the press and material manufacturer's guidelines for viscosity based on material, speed, and temperature.

7. Which type of operation is used for precision work on very small components, such as watch parts?

A. Step I - THE SCRAP STRIP

B. Sub Press Operations

C. Gages

D. Assembly Dies

8. Which step contains all information required to complete the die?

A. The Die Set

B. The Die Block

C. The Blanking Punch

D. The Piercing Punches

9. Name two essential die-set components and describe their functions.

A. Guides align the punch and die, and a stripper removes the part and resets stock

B. Bushings provide lubrication and springs shape the stock

C. Wear plates adjust reach and guides align the punch

D. Die shoe clamps the assembly and safety lock holds the press

10. Which document must be studied to determine exactly what operations were performed upon the workpiece previously?

A. Part print

B. Operation sheet

C. Layout

D. Design Drawings

SAMPLE

Answers

SAMPLE

1. A
2. A
3. D
4. C
5. D
6. D
7. B
8. A
9. A
10. A

SAMPLE

Explanations

SAMPLE

1. What lubrication strategies are common in stamping and their effects on wear and finish?

A. Flood or spray lubrication reduces friction and wear and helps control wrinkling and surface finish; dry lubrication can be used for certain materials or speeds but may increase wear

B. Dry lubrication only reduces wear

C. No lubrication reduces wear

D. Grease always reduces wear and improves finish

Friction control is the key idea here. In stamping, choosing the right lubrication strategy directly affects wear on the tooling and the quality of the finished part. Flood or spray lubrication creates a continuous film between the sheet and the die, which greatly reduces friction and tool wear. That lubricant film also helps manage material flow, which in turn reduces wrinkling and produces a more uniform surface finish by minimizing galling, scoring, and burnishing. Cooling is another benefit, helping to keep temperatures down during high-speed or high-load stamping. Dry lubrication is used in situations where liquids are undesirable or impractical—certain materials, special alloys, or higher-speed operations can call for dry or solid lubricants (like graphite or MoS2). These can reduce friction at the interface, but they don't always supply as much cooling or film strength as flood lubrication, so wear can be higher if the conditions aren't well matched. The finish can be more variable as well, depending on how well the dry lubricant stays in place and how it interacts with the surface. Grease and no lubrication aren't universally effective. Grease can smear or attract dirt, may not stay evenly on the interface at stamping speeds, and won't always provide the needed cooling or film strength, so wear and finish can suffer. No lubrication almost always leads to increased wear and poorer surface finish. So the best choice says that flood or spray lubrication reduces friction and wear and helps control wrinkling and surface finish; dry lubrication can be used for certain materials or speeds but may increase wear.

2. In the described material, which action is explicitly stated as occurring at STEP XI?

A. Piercing and Blanking

B. Honing and Finishing

C. Assembling and Screwing

D. Measuring and Checking

Step sequencing and the nature of stamping operations are being tested here. When a process map or material description explicitly mentions piercing and blanking at a given step, it means that the step is performing shearing operations on sheet metal: piercing creates holes by punching through the material, while blanking produces a flat blank by cutting it away from the sheet. These actions are characteristic of early, forming steps in a stamping line, not of finishing, assembly, or inspection stages. The other options correspond to finishing (honing and finishing), assembly (assembling and screwing), or measurement/inspection (measuring and checking), which do not match a step described as piercing and blanking.

SAMPLE

3. Which term defines a press tool or component for receiving blanks?

A. Die Design

B. Stampings

C. Die Block

D. Scrap Strip

The main idea being tested is identifying the tooling part that actually holds and positions the metal blank for forming. That role is fulfilled by the die block, the body of the die assembly that provides the cavity or shape and supports the blank as it's formed. Die design refers to creating the tooling layout, stampings are the finished parts produced, and a scrap strip is the waste material separated from the blank during punching. So, the term for a press tool or component that receives blanks is the die block.

4. Which operation smooths wavy edges of drawn metal parts?

A. Shaving

B. Broaching

C. Trimming

D. Horning

The operation that smooths wavy edges of drawn metal parts is trimming. After drawing, excess material often remains around the rim, creating a ridge or "flash" that makes the edge wavy and inconsistent. Trimming uses a punch and die to shear away this excess along the part's edge, producing a clean, uniform, straight edge and bringing the part to its intended size. Shaving can improve surface finish by removing small amounts, but it's typically used for fine surface conditions rather than reshaping or leveling the edge around the circumference. Broaching handles internal profiles or keyways, not edge finishing, and horning isn't the standard term for this edge-smoothing step.

5. What is the formula relating cutting speed, spindle speed, and workpiece diameter for turning, and how do you solve for N?

A. V equals pi times D times N divided by 1000, and N equals 1000 V divided by (pi D).

B. V equals D times N divided by pi, and N equals pi D V divided by 1000.

C. V equals 2 pi D N, and N equals V divided by (2 pi D).

D. V equals pi D N divided by 1000, and N equals 1000 V divided by (pi D).

The main idea is that cutting speed is the surface speed of the workpiece, which in turning comes from the surface traveling one circumference per revolution. Each revolution moves the surface a distance equal to π times the diameter, so the distance per minute is πDN when N is the spindle speed in revolutions per minute and D is the diameter. If D is in millimeters and you want V in meters per minute, you convert the millimeter distance to meters by dividing by 1000, giving V = (π D N) / 1000. Solving for N yields N = 1000 V / (π D). This form is consistent with using D in millimeters and V in meters per minute; if D were in meters, the 1000 would not be used.

SAMPLE

6. How would you select lubricant viscosity for a stamping operation?

A. Choose lubricant based on color and scent.

B. Use the lightest possible lubricant regardless of process.

C. Rely on trial-and-error to determine viscosity.

D. Follow the press and material manufacturer's guidelines for viscosity based on material, speed, and temperature.

The main idea is to base lubricant viscosity on the actual stamping conditions using manufacturer recommendations. In stamping, the right viscosity creates a lubricant film that protects tools and workpieces while allowing the metal to flow properly. The film must be thick enough to prevent metal-to-metal contact under load and heat, yet not so thick that it hampers fill of features or slows cooling and cycle time. Viscosity behavior with temperature is a key part: as temperature rises, lubricants thin out, so the recommended viscosity range accounts for how hot the tooling and material will get during operation. Manufacturers of presses and materials study how different metals behave under forming, counts of parts per minute, and typical operating temperatures to specify viscosity targets. They also consider the geometry of the part, the type of lubricant (oil, wax, emulsion), and how it will be applied. Following these guidelines gives a reliable starting point that aligns with the press design, tooling wear, part quality, and production rates. After initial use, you can fine-tune within the recommended range based on actual performance, but the baseline should come from those guidelines. Relying on surface attributes like color or scent isn't related to lubrication performance and won't ensure consistent results. Choosing the lightest lubricant by default can lead to inadequate protection under higher speeds or temps, and a purely trial-and-error approach wastes time and risks tool wear or part defects.

7. Which type of operation is used for precision work on very small components, such as watch parts?

A. Step I - THE SCRAP STRIP

B. Sub Press Operations

C. Gages

D. Assembly Dies

Precision work on very small components demands a dedicated, highly controlled forming process. Sub-press operations provide a secondary, often smaller and more rigid press setup that handles precision finishing steps on micro-features. This arrangement allows for finer tooling, closer register, slower and more stable strokes, and reduced deflection, which together yield consistent tolerances and clean edges on tiny parts like watch components. By performing delicate operations—such as fine trimming, deburring, or forming intricate details—on a separate, specialized press, precision is maintained without over-stressing or misaligning the parts in the main press. The other options don't fit because scrap-strip work is about removing waste, gages are measurement tools, and assembly dies are for putting parts together rather than performing the precision forming needed for tiny features.

SAMPLE

8. Which step contains all information required to complete the die?

A. The Die Set

B. The Die Block

C. The Blanking Punch

D. The Piercing Punches

In stamping, the die set is the complete assembly that defines how the die will be built and operate. It includes the die block with its cavity, the matching punches (blanking and piercing), bushings, backer plate, mounting hardware, and the necessary clearances and alignment details. With the die set, you have the full specification of both the forming cavity and the punching tools, so every part needed to complete the die is defined in one place. The die block alone only provides the cavity and lacks the accompanying punches and hardware. The individual punching tools—blanking punches and piercing punches—are essential components, but they don't by themselves outline the full die configuration. Therefore, the step that contains all information required to complete the die is the Die Set.

9. Name two essential die-set components and describe their functions.

A. Guides align the punch and die, and a stripper removes the part and resets stock

B. Bushings provide lubrication and springs shape the stock

C. Wear plates adjust reach and guides align the punch

D. Die shoe clamps the assembly and safety lock holds the press

Two essential die-set components are alignment guides and the stripper. Guides keep the punch and die perfectly aligned as the press cycles, ensuring they move true and stay parallel. This precise alignment is what gives you consistent part dimensions, clean stamping, and reduced wear from misalignment. The stripper acts as a part-releaser during the press return, pushing the finished part off the punch and resetting the stock for the next cycle. This prevents parts from sticking to the punch and keeps the production cycle smooth and automatic. Other features mentioned in the options aren't as central to the two critical functions described: bushings are mainly for guiding and supporting alignment rather than providing lubrication; springs return components and influence force but don't shape the stock; wear plates and the die shoe have important roles in wear management and mounting, but they don't define the core pair of alignment and part release that these two components provide.

10. Which document must be studied to determine exactly what operations were performed upon the workpiece previously?

A. Part print

B. Operation sheet

C. Layout

D. Design Drawings

To know exactly what operations were performed on the workpiece, you refer to the operation sheet. This document, often called a routing sheet, lists each step in the manufacturing sequence, the machines or workstations used, tools and setups, any required speeds and feeds, inspection points, and who performed each operation. It provides a complete processing history for that piece, allowing you to trace back precisely what happened to it. A part print, by contrast, focuses on geometry, features, tolerances, finishes, and dimensions—the "what" of the part design—not the sequence of processes used to make it. A layout describes the arrangement of equipment or flow in the shop, not the specific operations applied to a single workpiece. Design drawings convey design intent and specifications but still don't capture the full processing history.

SAMPLE

Next Steps

Congratulations on reaching the final section of this guide. You've taken a meaningful step toward passing your certification exam and advancing your career.

As you continue preparing, remember that consistent practice, review, and self-reflection are key to success. Make time to revisit difficult topics, simulate exam conditions, and track your progress along the way.

If you need help, have suggestions, or want to share feedback, we'd love to hear from you. Reach out to our team at hello@examzify.com.

Or visit your dedicated course page for more study tools and resources:

https://toolanddie.examzify.com

We wish you the very best on your exam journey. You've got this!

SAMPLE